Installation Instructions
Automation Housing IP65

Contents

1. Aluminium cover plate

1.1 Tool
Screwdriver torx for M4

1.2 Procedure

| Disassembly	Assembly
Remove the screws in the following order: 1. Screws with the number 1 2. Screws with the number 2 3. Screws with the number 3	To mount the aluminum cover plate, tighten the screws with a sealing ring in the following order: 1. Screws with the number 4 2. Screws with the number 5 3. Screws with the number 6 Tighten all screws with at least 1.5 Nm.

2. Button extension

2.1 Tool
Screwdriver torx for M3

Installation Instructions
## Automation Housing IP65

2.2 Procedure

Disassembly

Attention:
After loosening the button extensions, it must be fixed or held.

Gradually loosening all screws with the screwdriver.
Loosen the screws evenly on all sides.

Assembly

Inserting the button extension into the housing. The guide bolts must be inserted in the correct place.
Tighten the screws evenly with a sealing ring each with at least 1.5 Nm.

Disclaimer

Technical data are subject to modification and delivery subject to availability. Any liability that the data and illustrations are complete, actual or correct is excluded. Designations may be trademarks and/or copyrights of the respective manufacturer, the use of which by third parties for their own purposes may infringe the rights of such owner.

Contact

Christ Electronic Systems GmbH
Alpenstraße 34
87700 Memmingen

Phone:
+49 8331 8371-0 (Main Office)
+49 8331 8371-500 (Service)

Mail:
info@christ-es.de

Homepage:
https://www.christ-es.com

© Christ Electronic Systems GmbH